# Illinois Commerce Commission Pipeline Safety Field Trip Report

Operator: DYNEGY KENDALL ENERGY, LLC	Operator ID#: 32210					
Exit Meeting Contact: (Not Applicable)	Total Man Days: 0					
Pipeline Safety Representative(s): Matt Smith						
Company Representative to Receive Report: Tod Benninghoff	Emailed Date:					
Company Representative's Email Address: todd.benninghoff@dynegy.com	04/15/2014					

#### **Inspection Summary**

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection Annual Report Review	ICC Office	Matt Smith	Dynegy Kendall Energy	0	3/19/2014	

#### **Statement of Activities**

On March 19, 2014, Staff conducted a review of Dynegy Kendall Energy, LLC's Annual Report for calendar year 2013 to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. No deficiencies were discovered during this review.

## **INSPECTION FINDINGS**

### **Standard Inspection Annual Report Review**

#### Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

# PAST INSPECTION FINDINGS

#### Issue(s) Corrected:

NO ISSUES CORRECTED.

#### Notice Of Amendment(s) Corrected:

NO NOAs CORRECTED.

#### Notice of Violations(s) Corrected:

NO NOPVs CORRECTED.